

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
TAL PUKUR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MONI MALA MATH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
100 NISSET KALI MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BANTRA KABARSTAN	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
BIDHU BHUSAN GIRLS SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BYPASS KALI MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DAKSHIN SAHAPUR JELE PARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DASHNAGAR MANDIRPARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
GLASSGO PRINTING	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MAKARDAH ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MANDIR PARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NABARUNSANGH CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NATABARPAL ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHANPUR DASHNAGAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SOUTH SHANPUR SATCHASI PARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
TIKIAPARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
UTTAR BANTRA NABARUN SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DASHNAGAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HALIMAN SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
ISLAMIA HIGH SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
ST. VINCENT	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BANIAPARA MATH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BIDHAN SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DIC BUILDING	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
HALDIRAM SWEETS	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HATATH SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
IDBI BANK, P.T ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
JUGNU ASSOCIATION CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
JUNIOR BOYS CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MADAN SUNDAR SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MILAN MANDIR CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NARAYAN BUILDING	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NETAJI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEW FANCY CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SALE TAX BUILDING	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHIV MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
ANAMIKA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
ANNAPURNA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BANGABASI ATHLETIC CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BIRAM BITAN CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
DANU BOSE SRITI SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HOWRAH SADHIN SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KORAR BAGAN CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
LAXMAN DAS LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR ARCADIA NURSING HOME	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR BABA LOKENATH MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR PAGLA PHAUJ CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SANGHA MILAN CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
NEAR SANTI SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SARASWATI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SINGHA BAHINI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR THALASEMIA HOSPITAL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
OPPOSITE HOWRAH TOWN SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
PALLY BASI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
UROJAYEE CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
TARUN BYAHHAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
GOURI PADA (LITTLE BUD NURSERY SCHOOL)	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
H.S.C CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MAA KALI BAYAM SAMITI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR CONGRESS PARTY OFFICE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR PARKING ZONE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SAMLANI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SAYED BABA MAJAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SHIV MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
NEAR SITALA MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SWABHIMAN CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RABIN SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SANGHASRI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
SISHI GOLI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SUNRISE CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SUSHIL SMRITI SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SWARAJ SANGSAD CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
UDAR SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
UTSAHI SANGHA GALI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
AFTABUDDIN MUNSI LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
ASHU BOSE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
GOURI PADA MUKHERJEE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HAMINUDDIN MUNSHI LANE HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RASHAN GULZAR LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SREENATH PORAL LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
ANNAPURNA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
ARJA BALIKA VIDYALAYA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BELILIOUS LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BOYS SPORTING CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
BELILIOUS TENNIS CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HRIDAY KRISHNA BANERJEE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
INDIA CULTURAL CENTER .	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
JONJHOTI BALAK SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
KHIRTI BAS DHARA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
LAKHAN HAZRA RESIDENCE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
LAXMI NARAYAN VIDYALAYA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MILINI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
MUKTA RAM DEY LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SASTHI TALA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SABAIMILE CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BANTRA SISKHANIKATAN BOYS HIGH SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
B. PARK CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GHOSAL BAGAN CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
JHARNA SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KUCHI GHOSAL LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
KUCHIL SARKAR LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KUMAR PARA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MADHU SUDHAN PAUL CHOWDHURY LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MUNNA MEAT SHOP	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
N.P. COLLEGE B. PARK CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
ND COLLEGE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
PARAN SMRITI SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
PUSPASHREE CINEMA HALL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
RAJ LAKHI SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RAJ LAKSHMI SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RAJ LAXMI BALIKA VIDALAYA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RAJA RAM DAS LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
SANPUR JELEPARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SARADA SPORTING CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHANPURSHA SHAYAMA SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHANPURSHA YAMASANGA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
Z ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
AMAN SNITI SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
ANNAPURNA BAYAM SAMITY	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HOWRAH NETAJI SPORTING CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
HRIDAY MILAN SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
JOGIN MUKHERJEE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
JOGMAYA CINEMA HALL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
K B G CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
KADAMTALA HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KALI KUNDU LANE PETROL PUMP	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KALIKA BAHINI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NETAI CHARAN HOMEOPATHY COLLEGE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
PARBATI CINEMA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SABITA PRESS	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SAHAJATRI CLUB KALACHAND LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SARADAMANI ATHELETIC CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
SHYAMASHREE CINEMA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SITALA TARUN SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SREE DURGA BALIKA VIDYALAYA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
STUDENT AETHELIC CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
SUKIKAL BUS STAND	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
U.K.B CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
VIVEKANANDA AETHLETIC CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
ARANEYA SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
BAISHNAB PARA BAZAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
CHITTARANJAN BAYAM SAMITY CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DR. PRASENT BANERJEE OLD HOUSE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GADADHAR MISTRY LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
HALDERPARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HOWRAH VIVEKANANDA SISHU UDDYAN CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KHENJURTALA BALAKA SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NABIN BANARJEE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NARIKEL TALA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR BAISHNAB PARA BAZAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR BOSE BAZAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR GHOSH PARA VIDYASAGAR STACHU	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR GOURIYO MATH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR HOWRAH RABINDRA DESHBANDHU VIDYALAYA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR JANAKALYAN SAMITI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR JATIYA SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR KANCKLAL MATH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR KHELARGHAR MATH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR KHENJUR TALA BALAK SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR KISHARE SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR KOIPUKUR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR MANSHATALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR PARBATI CINEMA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SATIRTHA NETAJI SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR SATYA SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SISHU SATHI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SITALA SAMAITI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR YABAK SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
PARADISE GARMENTS	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SARADA SAMITY CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SARAT BOSE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SCASAMUSHI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
SISHU SATHI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SITALA SAMAITTY CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SWAMI VIVEKANANDA ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
TANTI PARA LANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
TETULTALA BYAM SMAITI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
VIVEKANANDA ASHRAM	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
VIVEKANANDA INSTITUTION SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
ACHARJEE PARA LANE, HOWRAH-1	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
ANNANDRA SAMILANI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BAISHABPARA MASJID	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BAISNAB PARA 1ST LANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BAKUL TALA PARK	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
CENTRAL HOWRAH BOYS UNITY CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
CHATRA MILONI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DHARMARAJ MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
FIVE STAR CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
GANDHI SMARAK SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GANGAMONI ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GOPAL BANERJEE LANE BARWARI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HOWRAH KUSTHA KUTHIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
KALI BABU BAZAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KALIKUNDU LANE PETROL PUMP	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KASUNDIA UNITED CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KHURUT POST OFFICE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
KHYAPA SAHGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KUNDU MEDICAL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MAHAKALI BALIKA VIDYALAYA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MANSHA TALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
MUKHERJEE BAGAN CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MULLICK PARA MUKTI SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NATUN JIBAN CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR CHATRA MILONI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR HERITAGE ACADEMY SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR KHURUT SASTHITALA MAIDAN	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR SASTHITALA BARWARI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR YUVA SANSAD CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
NEPAL SAHA LANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
PANCHANAN TALA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
PEOPLE NURSINGHOME	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
PRADIP SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
PRASANNA KUMAR DUTTA LANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
R.V.S.S CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RAMKRISHNAPUR KOUSAIK BAGAN	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SANTI NIKITAN CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
SHAKTI SANGHA RAM RAJA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SUBUJ JATRI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SUDHIR SMRITI SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SURKIKAL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
UDAY SANGHA CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
YUBA SANSAD CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
YUGAMANAB SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BHAI BHAI SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
BLACK ROSE CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
CHITTARANJAN BALAK SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KALI BABU BAZAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KHURUT UDAM SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
MITRA SANGH HOSPITAL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NETAJI SUBHAS ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RAM KRISHNA SPORTING CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SAPTARATHI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
SUBRTHO BALAK SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
ANANTARAM MUKHERJEE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BARODA BHATTACHARYA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
C.C. SINGHA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
K. B LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
K.B 2ND BYE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
K.B 3RD BYE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR AT 28 PARTY OFFICE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR AT AGRAGAMI BALAK SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR AT BHANRER MATH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR AT BISWA KALYAN SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR AT CHITTARANJAN BALAK SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR AT KALI KUNDU LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR AT NIRVIK GHOSTI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR AT S.A CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR BISWAKALYAN SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
R.B. SAHA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
R.B.S. 1ST BYE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
R.B.S. 2ND BYE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BANGO BASI CINEMA HALL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
BIJAY BHARAT SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BINAPANI CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BON BIHARI BOSE ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GANGA BHAWAN	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
HOWRAH FLOUR MILL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HOWRAH JAIL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HOWRAH MORGHE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
JAI HIND SPORTING CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
JAIN SWETAMBER HALL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NAV YUVAK SADAR SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RAJA HAT	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RASTRIYA VIDYALAYA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
ROUND TANK LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SAREE HAT	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SIDDHI DATRI KALI MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
AMBIKA HAI DU HIGH SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
AMBIKA HINDI HIGH SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
AMTALA HINDI HIGH SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BON BEHARI BASU ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GANGA DHAR MUKHARJEE ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
HOWRAH JUTE MILL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
JAIN VIDHYALAYA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NARA SINGHA BOSE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
PIRTALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
POST OFFICE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SANI MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHIKSHA NIKETAN SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHREE JAIN VIDHYALAYA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
SITALA MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
UMA CHARAN BOSE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
2, NO R.M.M. LANE(RAJIB GANDHI STACHU)	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
27 R.M.M. LANE (KAIPUKUR)	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
29/3/C R.M.M. LANE (KAIPUKUR)	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KAI PUKUR LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHIBPUR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHIBTALA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
58 BUS STAND	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BACK SIDE CHATTERJEEHAT	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BHABANI GIRL-S SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BHANESH KALI (NEAR)	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
CHATTERJEEHAT	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
CHOTO RAM TALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DOCTOR BARI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HAZAR HAT KALITALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
MANDIR TALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR BHABANI GIRLS- SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR BHANESH KALI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR NIMTALA MATH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
NEAR UNITED CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RAJAK SLUM	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SARADHA SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHIBPUR DINO BHONDHU SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
VANISH KALI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MANDIRTALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHIBPUR BAZAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHIBPUR TRAM DEPOT	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
DUKE ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GREWAL PUMP	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RAJ NARAYAN RAY SHOWDHURY GHAT ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SHIBPUR BAJAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
A. K ROY CHOWDHURY LANE, MANDIRTALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DHRUBA KUMAR PAUL LANE, MANDIRTALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MOLLA PARA LANE, MANDIRTALA, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NABIN NUKHERJEE LANE, MANDIRTALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
SHIBPUR ROAD, SHIBPUR, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
B.GARDEN	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
CARRY ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
CHATTERJEE HAT	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
CIRCULAR ROAD 2ND BYE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SARAT CHATTERJEE ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
B.GARDEN ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BACK SIDE OF RAMKRISHNA MISSION	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
BASUN GOLI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
CHARAK TALA MATH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DHARA BARI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
FRONT SIDE OF RAMKRISHNA MISSION	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
G.K.W. MAIN GATE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GURU DWARA MANDIR ANDUL ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
J.D.JONS & COM	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MAJAR HATE CLUB	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
MANSATALA MATH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NAOJAWAN SANGHA, ELIYAS PARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR BARGER PAINTS	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR DHURN BARI P.K..ROY CHOWDHURY 1ST LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR GARDEN SEVA SANSAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR HINDI SCHOOL, B.GARDEN MAIN GATE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR JANAPRIYA CLUB, NASKAR PARA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR JASADAMAYEE VIDAYALAYA SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR KOLEY BAZAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR LAXMI BHABAGATI HINDI PRIMARY SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR LIPI CENEMA JANA PARA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR MAJHAR HUTE CLUB, NASKAR PARA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR MANASHA TALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR RAMAKRISHNA SCHOOL	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
OPPOSITE SIDE OF RAMKRISHNA MISSION	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
TATUL TALA TARUN SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
B.GARDEN	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BHARPARA ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GOPAL LAL CHOWDHURY LANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KAJI PARA LANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
KEDAR NATH MUKHERJEE LANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MANILAL CHATTERJEE LANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RAM DHAN DAS LANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
RAM KUMAR GANGULY LANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
SHIBPUR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
TARAFDAR PARALANE, HOWRAH	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
ANDUL ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BANGAL PARALANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
LALKUTI(DAKSHIN BUXARAH)	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NABANARI TALA 1ST BYE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NABANARI TALA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SARAT CHATTERJEE ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
SOUTH BAKSARA 1ST BYE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SOUTH BAKSARA ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
THAKURPUKUR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
CHABAR RAMASHAR LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
CIRCULAR 6TH BYE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DUMURJALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GADADHAR MISTRI 2ND BYE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
GADHA DHAR MISTRY LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
H.P. GAS GODOWN	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KAJI BAGAN LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KASUNDIA 2ND BY LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KASUNDIA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
KAZI BAGAN LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MAHENDRA BHATTACHARYA ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NANDA LAL MUKHARJEE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
PRIYA NATH GHOSH LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
RAM KUMAR BHATTACHARJEE LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
SK PARA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
TANTIPARA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
THAKUR RAMKRISHNA LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
BALAPOLE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BANGA LAXMI PALLY	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BATORE BAYAM SAMITI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
BATORE HIROAD CROSSING	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
CHOWDHURY PARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DHALASAN	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
DR. PRABIR PAL HOUSE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
HIROAD BATORE CROSSING	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
HIROAD JANAGATE CROSSING	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
JALA KALI MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
K.LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
KUSUMPUR PARK	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitatio n pattern
LADONA RESTURENT	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
M.B ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MATHI PARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
MUKTARAM DEBNATH LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR BATORE HIROAD CROSSING	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR CHATTERJEE HAT	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR DR. SITAL GHOSH HOUSE	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
NEAR PRAM NAGAR	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Name of the Slum	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
NEAR TALPUKUR KALI MANDER	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
PHOPA PARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
PRAGATI SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
S.N.N GANGULY ROAD SANTRAGHICHI	The condition of living in the slum is unhygienic	Land belongs to the ULB	40	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

The proposed PMAY project would address the existing problems in the slum which includes lack of basic physical infrastructure and environmental betterment.

Site Location

The project slum is area in Howrah Municipal Corporation area.

Site Appraisal

1. Land of the project was belongs to WBSIDC and a part of it (0.12648 Sqkm) has been handed over to this Municipal Corporation by them for rehabilitation of the slum dwellers.
2. As the land of WBSIDC has been encroached by the slum dwellers and WBSIDC was unable to handover the land to entrepreneurs for the establishment of their Industries.
3. Condition of the slum was also not very good and the area will be slum free area if it is approved.
4. After implementation this project , this corporation, Our Municipal Corporation , WBSIDC , Slum Dwellers and Industrial Entrepreneurs all will be benefited.
5. More over C.I.C. & B.O.C. has also decided to take this slum as 1st PMAY Cluster project in the city.

Existing Slums Details

The environmental condition in the slums is poor. The slums lack basic civic amenities mainly drainage, thereby leading to water logging, mainly during rainy season. This has led to an unhygienic living condition in the slums. Most of the roads within slums are brick paved or kutchra road. Though there are sufficient streetlights available. Most of the population adopts unhygienic method for disposing their waste; thereby causing huge damage to health that ultimately leads to significant loss of man-days of work amongst others. Overall physical and social infrastructure is poor.

Project Land Particulars

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
1	J.N. MUKHERJEE ROAD, GHUSURY, HOWRAH, WB	1	539.57	26	40	core City	Residential	Notified	Land belongs to the ULB
2	RAM CHARAN NASKAR LANE GHUSURI HAORA	2	364.89	17	40	core City	Residential	Notified	Land belongs to the ULB
3	ABHIJATRI CLUB	3	1029.6	60	40	core City	Residential	Notified	Land belongs to the ULB
4	ASHTATOLA DURGA MANDIR	3	818.6	34	40	core City	Residential	Notified	Land belongs to the ULB
5	BABU DANGA	3	14.2	1	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
6	BANDER BAGAN	3	356.2	18	40	core City	Residential	Notified	Land belongs to the ULB
7	BANK OF INDIA(GHUSURI)	3	66	1	40	core City	Residential	Notified	Land belongs to the ULB
8	BARO BABAR MANDIR	3	9.4	1	40	core City	Residential	Notified	Land belongs to the ULB
9	BHATRI SANGHA MATH	3	9.4	1	40	core City	Residential	Notified	Land belongs to the ULB
10	CHANDRA CHALL CLUB	3	81.2	5	40	core City	Residential	Notified	Land belongs to the ULB
11	CHOROK TALA MATH	3	13.2	1	40	core City	Residential	Notified	Land belongs to the ULB
12	DASPARA	3	2555.3	122	40	core City	Residential	Notified	Land belongs to the ULB
13	DEBAGAN	3	3335.5	34	40	core City	Residential	Notified	Land belongs to the ULB
14	DIGHIR PARA	3	951.27	54	40	core City	Residential	Notified	Land belongs to the ULB
15	DURGA PALER MATH	3	2492.1	125	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
16	EVAREST SANGHA CLUB	3	11	1	40	core City	Residential	Notified	Land belongs to the ULB
17	FRIENDS CLUB	3	58.6	2	40	core City	Residential	Notified	Land belongs to the ULB
18	GHOSAL BAGAN FRIENDS CLUB	3	96.4	6	40	core City	Residential	Notified	Land belongs to the ULB
19	GHUSURI POST OFFICE	3	9.4	1	40	core City	Residential	Notified	Land belongs to the ULB
20	H.I.T PARK	3	65.6	5	40	core City	Residential	Notified	Land belongs to the ULB
21	HARI BASOR (MODYA BABUDANGA)	3	18.58	1	40	core City	Residential	Notified	Land belongs to the ULB
22	HARUR PUKUR	3	859.45	71	40	core City	Residential	Notified	Land belongs to the ULB
23	JALA PARA	3	287.76	11	40	core City	Residential	Notified	Land belongs to the ULB
24	KOYLA GOLI	3	510.28	11	40	core City	Residential	Notified	Land belongs to the ULB
25	KRISHNA BABHON	3	11.3	1	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
26	LOKENATH BHAVAN	3	23.6	1	40	core City	Residential	Notified	Land belongs to the ULB
27	MADHY BABU DANGA	3	37.8	1	40	core City	Residential	Notified	Land belongs to the ULB
28	MALI PANCH GHORA THANA	3	9.4	1	40	core City	Residential	Notified	Land belongs to the ULB
29	MONOHORA HIGH SCHOOL	3	150.5	3	40	core City	Residential	Notified	Land belongs to the ULB
30	NABA DALL CLUB	3	14.2	1	40	core City	Residential	Notified	Land belongs to the ULB
31	NAGARIK SAMITY CLUB	3	1278.6	24	40	core City	Residential	Notified	Land belongs to the ULB
32	NEAR NEW FRIENDS CLUB	3	9.4	1	40	core City	Residential	Notified	Land belongs to the ULB
33	NETAJI BIDYALAY	3	185.7	7	40	core City	Residential	Notified	Land belongs to the ULB
34	NEW FRIENDS CLUB	3	415.55	27	40	core City	Residential	Notified	Land belongs to the ULB
35	NEW STAR CLUB	3	671.3	36	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
36	PALER BAGAN MATH	3	117	9	40	core City	Residential	Notified	Land belongs to the ULB
37	POWER HOUSE	3	49.1	2	40	core City	Residential	Notified	Land belongs to the ULB
38	PRACHESTA ATHALETIC CLUB	3	24	2	40	core City	Residential	Notified	Land belongs to the ULB
39	PRAGATI SANGHA CLUB	3	691.58	32	40	core City	Residential	Notified	Land belongs to the ULB
40	RAJKOTHI	3	9.4	1	40	core City	Residential	Notified	Land belongs to the ULB
41	RAM BARI	3	36.23	2	40	core City	Residential	Notified	Land belongs to the ULB
42	SABANCALER MATH	3	87.69	4	40	core City	Residential	Notified	Land belongs to the ULB
43	SAHEB BAGAN MATH	3	221.3	20	40	core City	Residential	Notified	Land belongs to the ULB
44	SALKIA CHAUDRACHAL SAMITY	3	23.67	1	40	core City	Residential	Notified	Land belongs to the ULB
45	SALKIA KISHOR SANGHA	3	79.7	4	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
46	SATYABALA HOSPITAL	3	9.4	1	40	core City	Residential	Notified	Land belongs to the ULB
47	SATYABALA TELEPHONE BHOBAN	3	75.3	2	40	core City	Residential	Notified	Land belongs to the ULB
48	SHANTI RAKHI BAHINI CLUB	3	28.4	1	40	core City	Residential	Notified	Land belongs to the ULB
49	SHILPI DALL CLUB	3	18.9	1	40	core City	Residential	Notified	Land belongs to the ULB
50	SITALA MANDIR	3	112.92	6	40	core City	Residential	Notified	Land belongs to the ULB
51	TARUN SAMITY CLUB	3	389.93	20	40	core City	Residential	Notified	Land belongs to the ULB
52	BABU DAHGA	4	16.72	1	40	core City	Residential	Notified	Land belongs to the ULB
53	GHUSURI	4	454.23	13	40	core City	Residential	Notified	Land belongs to the ULB
54	SALKIA	4	1174.3	21	40	core City	Residential	Notified	Land belongs to the ULB
55	SHIV GOPAL BANRERJEE LANE	4	983.4	79	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
56	G.T. ROAD, SALKIA	5	94.4	1	40	core City	Residential	Notified	Land belongs to the ULB
57	HASNA BIBI LANE	5	83.61	2	40	core City	Residential	Notified	Land belongs to the ULB
58	SALKIA	5	27.87	2	40	core City	Residential	Notified	Land belongs to the ULB
59	BENARAS ROAD	6	37.16	1	40	core City	Residential	Notified	Land belongs to the ULB
60	DHARMATALA ROAD	6	439.43	19	40	core City	Residential	Notified	Land belongs to the ULB
61	GHOSH PARA LANE	6	576.1	12	40	core City	Residential	Notified	Land belongs to the ULB
62	UTTAM GHOSH LANE	6	55.2	3	40	core City	Residential	Notified	Land belongs to the ULB
63	AKSHAY CHATTERJEE LANE	7	108.11	4	40	core City	Residential	Notified	Land belongs to the ULB
64	A ROAD	7	46.45	1	40	core City	Residential	Notified	Land belongs to the ULB
65	B, ROAD KALABAGAN	7	362.76	13	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
66	D, ROAD	7	267.25	7	40	core City	Residential	Notified	Land belongs to the ULB
67	GHOSH PARA LANE	7	46.44	3	40	core City	Residential	Notified	Land belongs to the ULB
68	JANO KALYAN CLUB	7	37.8	1	40	core City	Residential	Notified	Land belongs to the ULB
69	F ROAD	8	1601.4	52	40	core City	Residential	Notified	Land belongs to the ULB
70	G ROAD	8	3845	157	40	core City	Residential	Notified	Land belongs to the ULB
71	H ROAD	8	2875	62	40	core City	Residential	Notified	Land belongs to the ULB
72	I ROAD	8	1057	22	40	core City	Residential	Notified	Land belongs to the ULB
73	J ROAD	8	398.9	18	40	core City	Residential	Notified	Land belongs to the ULB
74	K ROAD	8	3338.7	175	40	core City	Residential	Notified	Land belongs to the ULB
75	N ROAD	8	223	9	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
76	Q ROAD	8	2388.6	75	40	core City	Residential	Notified	Land belongs to the ULB
77	R ROAD	8	464.38	24	40	core City	Residential	Notified	Land belongs to the ULB
78	X ROAD	8	749.8	27	40	core City	Residential	Notified	Land belongs to the ULB
79	Y ROAD	8	778.3	35	40	core City	Residential	Notified	Land belongs to the ULB
80	KASHIPUR SANERGHAT	9	2412.3	46	40	core City	Residential	Notified	Land belongs to the ULB
81	NATHPARA	9	1306	53	40	core City	Residential	Notified	Land belongs to the ULB
82	LILUAH	9	3819.6	177	40	core City	Residential	Notified	Land belongs to the ULB
83	BAMUNGACHI	9	5711.3	315	40	core City	Residential	Notified	Land belongs to the ULB
84	BEHARAPARA	9	1330	48	40	core City	Residential	Notified	Land belongs to the ULB
85	RATHTALA	9	625.14	29	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
86	RAMCHANDRA ACHARJEE LANE, SALKIA, HOWRAH	10	153	7	40	core City	Residential	Notified	Land belongs to the ULB
87	ARABINDA ROAD, SALKIA, HOWRAH	11	600.77	43	40	core City	Residential	Notified	Land belongs to the ULB
88	TRIPURA ROY LANE, SALKIA, HOWRAH	11	1333.4	67	40	core City	Residential	Notified	Land belongs to the ULB
89	GHAT MAJHI LANE, SALKIA, HOWRAH	11	147.03	12	40	core City	Residential	Notified	Land belongs to the ULB
90	KALU PUKUR LANE, SALKIA, HOWRAH	11	622.44	49	40	core City	Residential	Notified	Land belongs to the ULB
91	KSHETRA CHATTERJEE LANE, SALKIA, HOWRAH	11	194.71	10	40	core City	Residential	Notified	Land belongs to the ULB
92	MUKHERJEE PARA LANE, SALKIA, HOWRAH	11	213.11	17	40	core City	Residential	Notified	Land belongs to the ULB
93	NILMONI MUKHESJEE ROAD, SALKIA, HOWRAH	11	308.18	14	40	core City	Residential	Notified	Land belongs to the ULB
94	PANJARI PARA LANE, SALKIA, HOWRAH	11	407.21	11	40	core City	Residential	Notified	Land belongs to the ULB
95	RAJ NARAYAN MUKHERJEE LANE, SALKIA, HOWRAH	11	581.9	41	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
96	SALKIA SCHOOLROAD, SALKIA, HOWRAH	11	9.3	2	40	core City	Residential	Notified	Land belongs to the ULB
97	ASHUTOSH MUKHERJEE LANE, SALKIA HOWRAH	12	78.98	5	40	core City	Residential	Notified	Land belongs to the ULB
98	HARDATTA RAY CHAMERIA ROAD, HOWRAH	13	93.94	7	40	core City	Residential	Notified	Land belongs to the ULB
99	MOULANA ABUL KALAM AZAD ROAD	13	346.59	12	40	core City	Residential	Notified	Land belongs to the ULB
100	SALKIA SCHOOL ROAD, 12 GOLABARI, HOWRAH	13	46.46	5	40	core City	Residential	Notified	Land belongs to the ULB
101	M. K. ROAD	14	91.07	7	40	core City	Residential	Notified	Land belongs to the ULB
102	G.T.ROAD (N) SAIKIA	15	342.8	14	40	core City	Residential	Notified	Land belongs to the ULB
103	RAM LAL MUKHERJEE LANE	15	14.86	2	40	core City	Residential	Notified	Land belongs to the ULB
104	GORA BAZAR	BOROUGH III	239.97	20	40	core City	Residential	Notified	Land belongs to the ULB
105	MARIYAS DAY SCHOOL	BOROUGH III	216.55	20	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
106	PNB	BOR OUG H III	672.67	51	40	core City	Residential	Notified	Land belongs to the ULB
107	VIKRAM VIDAYALAY SCHOOL	BOR OUG H III	492.91	52	40	core City	Residential	Notified	Land belongs to the ULB
108	BAROPALLY MATH	BOR OUG H III	311.62	15	40	core City	Residential	Notified	Land belongs to the ULB
109	DHANGOLA	BOR OUG H III	302.07	15	40	core City	Residential	Notified	Land belongs to the ULB
110	HARIJAN VIDYAMANDIR SCHOOL	BOR OUG H III	212.32	19	40	core City	Residential	Notified	Land belongs to the ULB
111	HARIJAN SHIV MANDIR SCHOOL	BOR OUG H III	425.07	24	40	core City	Residential	Notified	Land belongs to the ULB
112	NETAJI BALAK SANGHA	BOR OUG H III	55.73	3	40	core City	Residential	Notified	Land belongs to the ULB
113	THALASEMIA HOSPITAL	BOR OUG H III	177.53	15	40	core City	Residential	Notified	Land belongs to the ULB
114	URIYA PARA GOLI	BOR OUG H III	129.92	16	40	core City	Residential	Notified	Land belongs to the ULB
115	YOUNG BOYS CLUB	BOR OUG H III	51.09	2	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
116	B. PARK CLUB	BOR OUG H III	208.94	12	40	core City	Residential	Notified	Land belongs to the ULB
117	BANTRA BHARATI SANGHA CLUB	BOR OUG H III	398.43	8	40	core City	Residential	Notified	Land belongs to the ULB
118	DAKHIN BANTRA BALAK SANGHA	BOR OUG H III	172.73	14	40	core City	Residential	Notified	Land belongs to the ULB
119	DAKHIN BANTRA CLUB	BOR OUG H III	185.74	17	40	core City	Residential	Notified	Land belongs to the ULB
120	HOWRAH CRICKET ASSOCIATION CLUB	BOR OUG H III	18.58	2	40	core City	Residential	Notified	Land belongs to the ULB
121	JATIO SEBADAL CLUB	BOR OUG H III	274.49	10	40	core City	Residential	Notified	Land belongs to the ULB
122	JOGINDRA SRITI SIKHA MANDIR	BOR OUG H III	23.22	2	40	core City	Residential	Notified	Land belongs to the ULB
123	KHIRTALA CLUB	BOR OUG H III	471.17	25	40	core City	Residential	Notified	Land belongs to the ULB
124	N.D.COLEGE	BOR OUG H III	23.22	1	40	core City	Residential	Notified	Land belongs to the ULB
125	NETAJI JUBAK SANGHA CLUB	BOR OUG H III	369.7	7	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
126	SANGOSRI CLUB	BOR OUG H III	164.38	10	40	core City	Residential	Notified	Land belongs to the ULB
127	SANTI SANGHA CLUB	BOR OUG H III	285.1	15	40	core City	Residential	Notified	Land belongs to the ULB
128	SHRI KISHAN BHAGAT LANE	BOR OUG H III	352.82	14	40	core City	Residential	Notified	Land belongs to the ULB
129	SIMUL TALA CLUB	BOR OUG H III	34.36	3	40	core City	Residential	Notified	Land belongs to the ULB
130	TAL PUKUR	BOR OUG H III	299.99	8	40	core City	Residential	Notified	Land belongs to the ULB
131	MONI MALA MATH	BOR OUG H III	517.3	21	40	core City	Residential	Notified	Land belongs to the ULB
132	100 NISSET KALI MANDIR	BOR OUG H III	645.42	12	40	core City	Residential	Notified	Land belongs to the ULB
133	BANTRA KABARSTAN	BOR OUG H III	1507	57	40	core City	Residential	Notified	Land belongs to the ULB
134	BIDHU BHUSAN GIRLS SCHOOL	BOR OUG H III	117.97	6	40	core City	Residential	Notified	Land belongs to the ULB
135	BYPASS KALI MANDIR	BOR OUG H III	243.33	6	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
136	DAKSHIN SAHAPUR JELE PARA	BOR OUG H III	557.06	20	40	core City	Residential	Notified	Land belongs to the ULB
137	DASHNAGAR MANDIRPARA	BOR OUG H III	137.46	8	40	core City	Residential	Notified	Land belongs to the ULB
138	GLASSGO PRINTING	BOR OUG H III	182.99	12	40	core City	Residential	Notified	Land belongs to the ULB
139	MAKARDAH ROAD	BOR OUG H III	3194.5	154	40	core City	Residential	Notified	Land belongs to the ULB
140	MANDIR PARA	BOR OUG H III	253.57	14	40	core City	Residential	Notified	Land belongs to the ULB
141	NABARUNSANG H CLUB	BOR OUG H III	32.51	2	40	core City	Residential	Notified	Land belongs to the ULB
142	NATABARPAL ROAD	BOR OUG H III	44.56	4	40	core City	Residential	Notified	Land belongs to the ULB
143	SHANPUR DASHNAGAR	BOR OUG H III	51.08	4	40	core City	Residential	Notified	Land belongs to the ULB
144	SOUTH SHANPUR SATCHASI PARA	BOR OUG H III	993.86	59	40	core City	Residential	Notified	Land belongs to the ULB
145	TIKIAPARA	BOR OUG H III	628.88	14	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
146	UTTAR BANTRA NABARUN SANGHA	BOR OUG H III	190.38	4	40	core City	Residential	Notified	Land belongs to the ULB
147	DASHNAGAR	BOR OUG H III	12184	125	40	core City	Residential	Notified	Land belongs to the ULB
148	HALIMAN SCHOOL	BOR OUG H III	110.56	9	40	core City	Residential	Notified	Land belongs to the ULB
149	ISLAMIA HIGH SCHOOL	BOR OUG H III	56.19	8	40	core City	Residential	Notified	Land belongs to the ULB
150	ST. VINCENT	BOR OUG H III	27.86	2	40	core City	Residential	Notified	Land belongs to the ULB
151	BANIAPARA MATH	BOR OUG H III	200.67	5	40	core City	Residential	Notified	Land belongs to the ULB
152	BIDHAN SCHOOL	BOR OUG H III	138.15	10	40	core City	Residential	Notified	Land belongs to the ULB
153	DIC BUILDING	BOR OUG H III	9.29	1	40	core City	Residential	Notified	Land belongs to the ULB
154	HALDIRAM SWEETS	BOR OUG H III	96.45	8	40	core City	Residential	Notified	Land belongs to the ULB
155	HATATH SANGHA CLUB	BOR OUG H III	24.18	3	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
156	IDBI BANK, P.T ROAD	BOR OUG H III	60.4	2	40	core City	Residential	Notified	Land belongs to the ULB
157	JUGNU ASSOCIATION CLUB	BOR OUG H III	74.34	7	40	core City	Residential	Notified	Land belongs to the ULB
158	JUNIOR BOYS CLUB	BOR OUG H III	498.33	16	40	core City	Residential	Notified	Land belongs to the ULB
159	MADAN SUNDAR SCHOOL	BOR OUG H III	250.93	24	40	core City	Residential	Notified	Land belongs to the ULB
160	MILAN MANDIR CLUB	BOR OUG H III	18.59	1	40	core City	Residential	Notified	Land belongs to the ULB
161	NARAYAN BUILDING	BOR OUG H III	269.04	27	40	core City	Residential	Notified	Land belongs to the ULB
162	NETAJI CLUB	BOR OUG H III	13.02	2	40	core City	Residential	Notified	Land belongs to the ULB
163	NEW FANCY CLUB	BOR OUG H III	46.46	2	40	core City	Residential	Notified	Land belongs to the ULB
164	SALE TAX BUILDING	BOR OUG H III	278.48	27	40	core City	Residential	Notified	Land belongs to the ULB
165	SHIV MANDIR	BOR OUG H III	153.04	9	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
166	ANAMIKA CLUB	BOR OUG H III	112.16	10	40	core City	Residential	Notified	Land belongs to the ULB
167	ANNAPURNA CLUB	BOR OUG H III	89.28	5	40	core City	Residential	Notified	Land belongs to the ULB
168	BANGABASI ATHELATIC CLUB	BOR OUG H III	398.29	40	40	core City	Residential	Notified	Land belongs to the ULB
169	BIRAM BITAN CLUB	BOR OUG H III	364.16	15	40	core City	Residential	Notified	Land belongs to the ULB
170	DANU BOSE SRITI SANGHA	BOR OUG H III	132.62	11	40	core City	Residential	Notified	Land belongs to the ULB
171	HOWRAH SADHIN SANGHA CIUB	BOR OUG H III	131.15	7	40	core City	Residential	Notified	Land belongs to the ULB
172	KORAR BAGAN CLUB	BOR OUG H III	2482.6	128	40	core City	Residential	Notified	Land belongs to the ULB
173	LAXMAN DAS LANE	BOR OUG H III	40.86	7	40	core City	Residential	Notified	Land belongs to the ULB
174	NEAR ARCADIA NURSING HOME	BOR OUG H III	195.1	14	40	core City	Residential	Notified	Land belongs to the ULB
175	NEAR BABA LOKENATH MANDIR	BOR OUG H III	106.84	8	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
176	NEAR PAGLA PHAUJ CLUB	BOR OUG H III	195.74	2	40	core City	Residential	Notified	Land belongs to the ULB
177	NEAR SANGHA MILAN CLUB	BOR OUG H III	38.53	2	40	core City	Residential	Notified	Land belongs to the ULB
178	NEAR SANTI SANGHA CLUB	BOR OUG H III	658.71	37	40	core City	Residential	Notified	Land belongs to the ULB
179	NEAR SARASWATI CLUB	BOR OUG H III	373.68	7	40	core City	Residential	Notified	Land belongs to the ULB
180	NEAR SINGHA BAHINI CLUB	BOR OUG H III	251.64	17	40	core City	Residential	Notified	Land belongs to the ULB
181	NEAR THALASEMIA HOSPITAL	BOR OUG H III	1131.6	69	40	core City	Residential	Notified	Land belongs to the ULB
182	OPPOSITE HOWRAH TOWN SCHOOL	BOR OUG H III	55.74	2	40	core City	Residential	Notified	Land belongs to the ULB
183	PALLY BASI CLUB	BOR OUG H III	172.8	5	40	core City	Residential	Notified	Land belongs to the ULB
184	UROJAYEE CLUB	BOR OUG H III	1195.4	61	40	core City	Residential	Notified	Land belongs to the ULB
185	TARUN BYAHHAR	BOR OUG H III	12.07	1	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
186	GOURI PADA (LITTLE BUD NURSERY SCHOOL)	BOR OUG H III	88.41	8	40	core City	Residential	Notified	Land belongs to the ULB
187	H.S.C CLUB	BOR OUG H III	13.37	1	40	core City	Residential	Notified	Land belongs to the ULB
188	MAA KALI BAYAM SAMITI	BOR OUG H III	346.97	11	40	core City	Residential	Notified	Land belongs to the ULB
189	NEAR CONGRESS PARTY OFFICE	BOR OUG H III	285.64	17	40	core City	Residential	Notified	Land belongs to the ULB
190	NEAR PARKING ZONE	BOR OUG H III	20.42	2	40	core City	Residential	Notified	Land belongs to the ULB
191	NEAR SAMLANI CLUB	BOR OUG H III	178.36	2	40	core City	Residential	Notified	Land belongs to the ULB
192	NEAR SAYED BABA MAJAR	BOR OUG H III	97.54	1	40	core City	Residential	Notified	Land belongs to the ULB
193	NEAR SHIV MANDIR	BOR OUG H III	131.86	15	40	core City	Residential	Notified	Land belongs to the ULB
194	NEAR SITALA MANDIR	BOR OUG H III	528.93	11	40	core City	Residential	Notified	Land belongs to the ULB
195	NEAR SWABHIMAN CLUB	BOR OUG H III	11.14	1	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
196	RABIN SANGHA CLUB	BOR OUG H III	3.71	1	40	core City	Residential	Notified	Land belongs to the ULB
197	SANGHASRI CLUB	BOR OUG H III	151.84	13	40	core City	Residential	Notified	Land belongs to the ULB
198	SISHI GOLI	BOR OUG H III	120.59	17	40	core City	Residential	Notified	Land belongs to the ULB
199	SUNRISE CLUB	BOR OUG H III	60.38	1	40	core City	Residential	Notified	Land belongs to the ULB
200	SUSHIL SMRITI SANGHA CLUB	BOR OUG H III	256.99	11	40	core City	Residential	Notified	Land belongs to the ULB
201	SWARAJ SANGSAD CLUB	BOR OUG H III	200.72	6	40	core City	Residential	Notified	Land belongs to the ULB
202	UDAR SANGHA CLUB	BOR OUG H III	102.18	8	40	core City	Residential	Notified	Land belongs to the ULB
203	UTSAHI SANGHA GALI	BOR OUG H III	162.61	5	40	core City	Residential	Notified	Land belongs to the ULB
204	AFTABUDDIN MUNSI LANE	BOR OUG H III	129.04	7	40	core City	Residential	Notified	Land belongs to the ULB
205	ASHU BOSE LANE	BOR OUG H III	9877.7	64	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
206	GOURI PADA MUKHERJEE LANE	BOR OUG H III	18.58	1	40	core City	Residential	Notified	Land belongs to the ULB
207	HAMINUDDIN MUNSHI LANE HOWRAH	BOR OUG H III	535.83	42	40	core City	Residential	Notified	Land belongs to the ULB
208	RASHAN GULZAR LANE	BOR OUG H III	407.28	30	40	core City	Residential	Notified	Land belongs to the ULB
209	SREENATH PORAL LANE	BOR OUG H III	142.27	10	40	core City	Residential	Notified	Land belongs to the ULB
210	ANNAPURNA CLUB	BOR OUG H III	330.68	20	40	core City	Residential	Notified	Land belongs to the ULB
211	ARJA BALIKA VIDYALAYA	BOR OUG H III	18.58	1	40	core City	Residential	Notified	Land belongs to the ULB
212	BELILIOUS LANE	BOR OUG H III	62.24	2	40	core City	Residential	Notified	Land belongs to the ULB
213	BOYS SPORTING CLUB	BOR OUG H III	32.51	2	40	core City	Residential	Notified	Land belongs to the ULB
214	BELILIOUS TENNIS CLUB	BOR OUG H III	37.15	2	40	core City	Residential	Notified	Land belongs to the ULB
215	HRIDAY KRISHNA BANERJEE LANE	BOR OUG H III	406.83	23	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
216	INDIA CULTURAL CENTER	BOR OUG H III	76.17	8	40	core City	Residential	Notified	Land belongs to the ULB
217	JONJHOTI BALAK SANGHA	BOR OUG H III	15.79	1	40	core City	Residential	Notified	Land belongs to the ULB
218	KHIRTI BAS DHARA LANE	BOR OUG H III	9.29	1	40	core City	Residential	Notified	Land belongs to the ULB
219	LAKHAN HAZRA RESIDENCE	BOR OUG H III	218.32	2	40	core City	Residential	Notified	Land belongs to the ULB
220	LAXMI NARAYAN VIDYALAYA	BOR OUG H III	281.48	6	40	core City	Residential	Notified	Land belongs to the ULB
221	MILINI CLUB	BOR OUG H III	18.58	2	40	core City	Residential	Notified	Land belongs to the ULB
222	MUKTA RAM DEY LANE	BOR OUG H III	18.58	2	40	core City	Residential	Notified	Land belongs to the ULB
223	SASTHI TALA CLUB	BOR OUG H III	55.74	2	40	core City	Residential	Notified	Land belongs to the ULB
224	SABAIMILE CLUB	BOR OUG H III	40.85	4	40	core City	Residential	Notified	Land belongs to the ULB
225	BANTRA SISKHANIKATA N BOYS HIGH SCHOOL	BOR OUG H III	139.35	1	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
226	B. PARK CLUB	BOR OUG H III	430.1	10	40	core City	Residential	Notified	Land belongs to the ULB
227	GHOSAL BAGAN CLUB	BOR OUG H III	503.49	16	40	core City	Residential	Notified	Land belongs to the ULB
228	JHARNA SANGHA CLUB	BOR OUG H III	903.6	42	40	core City	Residential	Notified	Land belongs to the ULB
229	KUCHI GHOSAL LANE	BOR OUG H III	112.4	2	40	core City	Residential	Notified	Land belongs to the ULB
230	KUCHIL SARKAR LANE	BOR OUG H III	251.98	4	40	core City	Residential	Notified	Land belongs to the ULB
231	KUMAR PARA LANE	BOR OUG H III	200.02	2	40	core City	Residential	Notified	Land belongs to the ULB
232	MADHU SUDHAN PAUL CHOWDHURY LANE	BOR OUG H III	22.28	2	40	core City	Residential	Notified	Land belongs to the ULB
233	MUNNA MEAT SHOP	BOR OUG H III	274.03	11	40	core City	Residential	Notified	Land belongs to the ULB
234	N.P. COLLEGE B. PARK CLUB	BOR OUG H III	218.31	5	40	core City	Residential	Notified	Land belongs to the ULB
235	ND COLLEGE	BOR OUG H III	139.34	3	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
236	PARAN SMRITI SCHOOL	BOR OUG H III	199.27	2	40	core City	Residential	Notified	Land belongs to the ULB
237	PUSPASHREE CINEMA HALL	BOR OUG H III	217.39	2	40	core City	Residential	Notified	Land belongs to the ULB
238	RAJ LAKHI SCHOOL	BOR OUG H III	78.96	2	40	core City	Residential	Notified	Land belongs to the ULB
239	RAJ LAKSHMI SCHOOL	BOR OUG H III	434.53	5	40	core City	Residential	Notified	Land belongs to the ULB
240	RAJ LAXMI BALIKA VIDALAYA	BOR OUG H III	539.67	13	40	core City	Residential	Notified	Land belongs to the ULB
241	RAJA RAM DAS LANE	BOR OUG H III	359.52	3	40	core City	Residential	Notified	Land belongs to the ULB
242	SANPUR JELEPARA	BOR OUG H III	215.52	8	40	core City	Residential	Notified	Land belongs to the ULB
243	SARADA SPORTING CLUB	BOR OUG H III	492.52	12	40	core City	Residential	Notified	Land belongs to the ULB
244	SHANPURSHA SHAYAMA SANGHA	BOR OUG H III	13.93	1	40	core City	Residential	Notified	Land belongs to the ULB
245	SHANPURSHA YAMASANGA	BOR OUG H III	120.77	2	40	core City	Residential	Notified	Land belongs to the ULB

Slum No.	Name of Slum	WARD NO	Area Sqm	No. of Household	Age in years	Whether located in core City/Town or Fringe area	Type of Area surrounding Slum	Is the slum Notified/ Declared	Ownership of Land where Slum is located
246	Z ROAD	BOR OUGH III	55.74	2	40	core City	Residential	Notified	Land belongs to the ULB
247	AMAN SNITI SANGHA	24	37.16	1	40	core City	Residential	Notified	Land belongs to the ULB
248	ANNAPURNA BAYAM SAMITY	24	107.75	5	40	core City	Residential	Notified	Land belongs to the ULB
249	HOWRAH NETAJI SPORTING CLUB	24	91.02	4	40	core City	Residential	Notified	Land belongs to the ULB
250	HRIDAY MILAN SANGHA CLUB	24	261.96	10	40	core City	Residential	Notified	Land belongs to the ULB
251	JOGIN MUKHERJEE LANE	24	167.22	1	40	core City	Residential	Notified	Land belongs to the ULB
252	JOGMAYA CINEMA HALL	24	102.17	5	40	core City	Residential	Notified	Land belongs to the ULB
253	K B G CLUB	24	27.87	1	40	core City	Residential	Notified	Land belongs to the ULB
254	KADAMTALA HOWRAH	24	111.76	1	40	core City	Residential	Notified	Land belongs to the ULB
255	KALI KUNDU LANE PETROL PUMP	24	23.22	1	40	core City	Residential	Notified	Land belongs to the ULB