

Sl.No	Name of the Slums	Status	Land	Age in years	National Highway	Status of Housings	Road Status	Habitation pattern
10	DANGAPARA ARUNADOY SANGHA	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
11	SYBON ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
12	ANANDAPALLY	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
13	RAMKRISHNA PARK	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

No	Name of the Slums	Status	Land	Age in years	National High Way	Status of Housings	Road Status	Habitation pattern
14	SREE PALLY	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
15	RAAMKRISHNA PALLY AMBAGAN	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
16	SREE PALLY (PASCHIM)	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
17	SITALA MANDIR	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
18	RAMKRISHNA PARK ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

I.No	Name of the Slums	Status	Land	Age in years	National High Way	Status of Housings	Road Status	Habitation pattern
						asbestos/tiles on roof		
19	RAMKRISHNA PALLY 2 NO ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
20	RAMKRISHNA PARK 2	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
21	NILGUNJ ROAD ORAW PARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
22	MORAL PARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

S.No	Name of the Slums	Status	Land	Age in years	National High Way	Status of Housings	Road Status	Habitation pattern
23	GOLDERPARA-2	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
24	GOLDERPARA-3	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
25	DAKSHIN PALLY	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
26	SAHAPARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
27	DAKSHIN PALLY PASCHIM	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Sl.No	Name of the Slums	Status	Land	Age in years	National High Way	Status of Housings	Road Status	Habitation pattern
						asbestos/tiles on roof		
28	DAKSHIN PALLY MADHYA	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
29	BIDHAN PARA	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
30	ASHISH COLONY	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
31	SARAT BOSE COLONY 1	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Sl.No	Name of the Slums	Status	Land	Age in years	National High Way	Status of Housings	Road Status	Habitation pattern
32	DAKSHIN PALLY 2	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
33	PURBACHAL	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
34	ARUNACHAL	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
35	DUTTA BAGAN	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
36	THANA ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

L.No	Name of the Slums	Status	Land	Age in years	National High Way	Status of Housings	Road Status	Habitation pattern
						asbestos/tiles on roof		
37	IT KHOLA	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
38	P.K. BISWAS ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
39	BALAK NATH TALA	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
40	RASKHOLA BY LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

Sl.No	Name of the Slums	Status	Land	Age in years	National High Way	Status of Housings	Road Status	Habitation pattern
41	THANA ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
42	MADHUSUDAN MUKHERJEE ROAD	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
43	RAGHUNATH SHAW BASTEE	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
44	3 NO GOVT. COLONY	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space
45	P.N. MUKHERJEE BY LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

L.No	Name of the Slums	Status	Land	Age in years	National High Way	Status of Housings	Road Status	Habitation pattern
						asbestos/tiles on roof		
46	PANCHANAN TALA BY LANE	The condition of living in the slum is unhygienic	Land belongs to the ULB	30	The National Highway - 2 is 5.0 kms away	Major population is living in huts, made of darma / bricks with tin sheets and asbestos/tiles on roof	Majority portion of roads are brick paved or damaged roads.	Habitation pattern in the slums is congested with insufficient open space

The proposed PMAY project would address the existing problems in the slum which includes lack of basic physical infrastructure and environmental betterment.

Annex

Site Location

The project slum is situated at core area in Municipal area. project slum location: Selected slums are demarked with coloured circle. Map of Slums boundaries within Khardah Municipality boundary is given below:

Site Appraisal

1. Land of the project was belongs to WBSIDC and a part of it (3.21 Acre) has been handed over to this municipality by them for rehabilitation of the slum dwellers.
2. As the land of WBSIDC has been encroached by the slum dwellers and WBSIDC was unable to handover the land to entrepreneurs for the establishment of their Industries.
3. Condition of the slum was also not very good and the area will be slum free area if it is approved.
4. After implementation this project , this corporation, Our Municipality , WBSIDC , Slum Dwellers and Industrial Entrepreneurs all will be benefited.
5. More over C.I.C. & B.O.C. has also decided to take this slum as 1st PMAY Cluster project in the city.

Maps of Slums and Non-Slums which are taken 1st DPR tenure for the year 2015-16 are given below :-

KHARDAH MUNICIPALITY WARD MAP




Legend

- Road
- Railway
- Slum_Boundary
- River
- Canal
- Ward_Boundary

HOOGHLY RIVER

RAILWAY TRACK

BT ROAD



0 112.5 225 450 675 900 Meters

Existing Slums Details

The environmental condition in the slums is poor. The slums lack basic civic amenities mainly drainage, thereby leading to water logging, mainly during rainy season. This has led to an unhygienic living condition in the slums. Most of the roads within slums are brick paved or kutchra road. Though there are sufficient streetlights available. Most of the population adopts unhygienic method for disposing their waste; thereby causing huge damage to health that ultimately leads to significant loss of man-days of work amongst others. Overall physical and social infrastructure is poor.

Project Land Particulars

S L N o.	W ar d N u m b e r	Slu m C o d e	Slum Name	AREA in Sq Mt	Age of the Slu m (in Yea rs)	Wheth er located in core City/T own or Fringe area	Type of Area surroundi ng Slum	Is the slum Notified / Declare d	Ownership of Land where Slum is located
1	1	001	KHATAL BUSTEE	7673.4 877	30	core City	Residentia 1	Notified	Land belongs to the ULB
2	1	008	KUNBHAKA R BUSTEE	2466.3 173	30	core City	Residentia 1	Notified	Land belongs to the ULB
3	1	011	BARIK BUSTEE	12098. 5631	30	core City	Residentia 1	Notified	Land belongs to the ULB
4	1	012	M.P.SCHOO L BUSTEE	12336. 1057	30	core City	Residentia 1	Notified	Land belongs to the ULB
5	1	013	WAHED BUSTEE	19027. 7999	30	core City	Residentia 1	Notified	Land belongs to the ULB

S L N o.	W ar d N u m b e r	Slu m C o d e	Slum Name	AREA in Sq Mt	Age of the Slu m (in Yea rs)	Wheth er located in core City/T own or Fringe area	Type of Area surroundi ng Slum	Is the slum Notified / Declare d	Ownership of Land where Slum is located
6	1	015	CHANDU BUSTEE	12371.4639	30	core City	Residentia 1	Notified	Land belongs to the ULB
7	1	017	DEWAN BUSTEE	1931.7324	30	core City	Residentia 1	Notified	Land belongs to the ULB
8	3	021	DANGAPAR A CHOWDHU RY MORE	15200.7145	30	core City	Residentia 1	Notified	Land belongs to the ULB
9	3	022	DANGAPAR A GOVT.COLO NY	5963.3143	30	core City	Residentia 1	Notified	Land belongs to the ULB
10	3	113	DANGAPAR A ARUNADOY SANGHA	7555.7884	30	core City	Residentia 1	Notified	Land belongs to the ULB
11	4	023	SYBON ROAD	8066.5929	30	core City	Residentia 1	Notified	Land belongs to the ULB
12	4	024	ANANDAPA LLY	20756.2745	30	core City	Residentia 1	Notified	Land belongs to the ULB
13	4	026	RAMKRISH NA PARK	6443.4987	30	core City	Residentia 1	Notified	Land belongs to the ULB
14	4	027	SREE PALLY	14449.5527	30	core City	Residentia 1	Notified	Land belongs to the ULB

S L N o.	W a r d N u m b e r	Slu m C o d e	Slum Name	AREA in Sq Mt	Age of the Slu m (in Yea rs)	Wheth er located in core City/T own or Fringe area	Type of Area surroundi ng Slum	Is the slum Notified / Declare d	Ownership of Land where Slum is located
15	4	029	RAAMKRISHNA PALLY AMBAGAN	12838. 1045	30	core City	Residentia 1	Notified	Land belongs to the ULB
16	4	032	SREE PALLY (PASCHIM)	14381. 1262	30	core City	Residentia 1	Notified	Land belongs to the ULB
17	4	033	SITALA MANDIR	10097. 7943	30	core City	Residentia 1	Notified	Land belongs to the ULB
18	4	034	RAMKRISH NA PARK ROAD	7814.8 943	30	core City	Residentia 1	Notified	Land belongs to the ULB
19	4	035	RAMKRISH NA PALLY 2 NO ROAD	5060.1 818	30	core City	Residentia 1	Notified	Land belongs to the ULB
20	4	115	RAMKRISH NA PARK 2	14206. 7246	30	core City	Residentia 1	Notified	Land belongs to the ULB
21	5	038	NILGUNJ ROAD ORAW PARA	2893.9 627	30	core City	Residentia 1	Notified	Land belongs to the ULB
22	5	039	MORAL PARA	3303.1 559	30	core City	Residentia 1	Notified	Land belongs to the ULB
23	5	040	GOLDERPA RA-2	3609.8 004	30	core City	Residentia 1	Notified	Land belongs to the ULB

S L N o.	W ar d N u m b e r	Slu m C o d e	Slum Name	AREA in Sq Mt	Age of the Slu m (in Yea rs)	Wheth er located in core City/T own or Fringe area	Type of Area surroundi ng Slum	Is the slum Notified / Declare d	Ownership of Land where Slum is located
24	5	041	GOLDERPA RA-3	3866.4 532	30	core City	Residentia 1	Notified	Land belongs to the ULB
25	8	052	DAKSHIN PALLY	9793.6 367	30	core City	Residentia 1	Notified	Land belongs to the ULB
26	8	053	SAHAPARA	2207.7 544	30	core City	Residentia 1	Notified	Land belongs to the ULB
27	8	054	DAKSHIN PALLY PASCHIM	6726.2 758	30	core City	Residentia 1	Notified	Land belongs to the ULB
28	8	055	DAKSHIN PALLY MADHYA	2698.4 765	30	core City	Residentia 1	Notified	Land belongs to the ULB
29	8	056	BIDHAN PARA	6726.2 758	30	core City	Residentia 1	Notified	Land belongs to the ULB
30	11	063	ASHISH COLONY	5971.0 381	30	core City	Residentia 1	Notified	Land belongs to the ULB
31	11	064	SARAT BOSE COLONY 1	4875.9 81	30	core City	Residentia 1	Notified	Land belongs to the ULB
32	12	070	DAKSHIN PALLY 2	2124.6 769	30	core City	Residentia 1	Notified	Land belongs to the ULB

S L N o.	W ar d N u m b e r	Slu m C o d e	Slum Name	AREA in Sq Mt	Age of the Slu m (in Yea rs)	Wheth er located in core City/T own or Fringe area	Type of Area surroundi ng Slum	Is the slum Notified / Declare d	Ownership of Land where Slum is located
33	12	071	PURBACHA L	24466.4816	30	core City	Residentia 1	Notified	Land belongs to the ULB
34	12	075	ARUNACHA L	8507.6165	30	core City	Residentia 1	Notified	Land belongs to the ULB
35	14	083	DUTTA BAGAN	4710.0888	30	core City	Residentia 1	Notified	Land belongs to the ULB
36	14	84	THANA ROAD	20480.9128	30	core City	Residentia 1	Notified	Land belongs to the ULB
37	14	085	IT KHOLA	31609.6025	30	core City	Residentia 1	Notified	Land belongs to the ULB
38	15	089	P.K. BISWAS ROAD	6604.6546	30	core City	Residentia 1	Notified	Land belongs to the ULB
39	17	091	BALAK NATH TALA	4670.0358	30	core City	Residentia 1	Notified	Land belongs to the ULB
40	18	095	RASKHOLA BY LANE	4682.8148	30	core City	Residentia 1	Notified	Land belongs to the ULB
41	19	096	THANA ROAD	6238.9173	30	core City	Residentia 1	Notified	Land belongs to the ULB

S L N o.	W a r d N u m b e r	Slu m C o d e	Slum Name	AREA in Sq Mt	Age of the Slu m (in Yea rs)	Wheth er located in core City/T own or Fringe area	Type of Area surroundi ng Slum	Is the slum Notified / Declare d	Ownership of Land where Slum is located
42	19	122	MADHUSUD AN MUKHERJE E ROAD	8128.9 373	30	core City	Residentia 1	Notified	Land belongs to the ULB
43	20	097	RAGHUNAT H SHAW BASTEE	2905	30	core City	Residentia 1	Notified	Land belongs to the ULB
44	21	099	3 NO GOVT. COLONY	5037.0 739	30	core City	Residentia 1	Notified	Land belongs to the ULB
45	22	104	P.N. MUKHERJE E BY LANE	2783.7 946	30	core City	Residentia 1	Notified	Land belongs to the ULB
46	22	108	PANCHANA N TALA BY LANE	1652.6 103	30	core City	Residentia 1	Notified	Land belongs to the ULB

Migration

Maximum dwellers have migrated from rural areas due to lack of employment in agriculture sector. All household had migrated from rural to urban area. Majority of the population of this slum is living for more than 30 years in this slum. Hence, dwellers are now permanently depending on slums. This justifies as a parameter on the importance of Slum for In situ development.

Housing Status

Housing is the constituent of the social infrastructure of the economy. Like the other constituents, such as the system of education and health, housing also can either reduce or enhance the disparities in the society.

House Type /Structure

KHATAL BUSTEE(Slum Code:-001)		
Semi Pucca	Kachha	Total
1		1
KUNBHAKAR BUSTEE(Slum Code:-008)		
Semi Pucca	Kachha	Total
3		3
BARIK BUSTEE(Slum Code:-011)		
Semi Pucca	Kachha	Total
2	0	2
M.P.SCHOOL BUSTEE(Slum Code:-012)		
Semi Pucca	Kachha	Total
1	0	1
WAHED BUSTEE(Slum Code:-013)		
Semi Pucca	Kachha	Total
4	3	7
CHANDU BUSTEE(Slum Code:-015)		
Semi Pucca	Kachha	Total
6	0	6
DEWAN BUSTEE(Slum Code:-017)		
Semi Pucca	Kachha	Total
3	0	3
DANGAPARA CHOWDHURY MORE(Slum Code:-021)		
Semi Pucca	Kachha	Total
6	0	6
DANGAPARA GOVT.COLONY(Slum Code:-022)		
Semi Pucca	Kachha	Total
7	1	8
DANGAPARA ARUNADOY SANGHA(Slum Code:-113)		
Semi Pucca	Kachha	Total
5	0	5

SYBON ROAD(Slum Code:-023)		
Semi Pucca	Kachha	Total
1	0	1
ANANDAPALLY(Slum Code:-024)		
Semi Pucca	Kachha	Total
5	0	5

RAMKRISHNA PARK(Slum Code:-026)		
Semi Pucca	Kachha	Total
4	0	4
SREE PALLY(Slum Code:-027)		
Semi Pucca	Kachha	Total
4	0	4
RAAMKRISHNA PALLY AMBAGAN(Slum Code:-029)		
Semi Pucca	Kachha	Total
6	1	7
SREE PALLY (PASCHIM)(Slum Code:-032)		
Semi Pucca	Kachha	Total
3	0	3
SITALA MANDIR(Slum Code:-033)		
Semi Pucca	Kachha	Total
1	0	1
RAMKRISHNA PARK ROAD(Slum Code:-034)		
Semi Pucca	Kachha	Total
9	0	9
RAMKRISHNA PALLY 2 NO ROAD		
Semi Pucca	Kachha	Total
5	1	6
RAMKRISHNA PARK 2(Slum Code:-115)		
Semi Pucca	Kachha	Total
6	0	6
NILGUNJ ROAD ORAW PARA(Slum Code:-038)		
Semi Pucca	Kachha	Total
5	1	6
MORAL PARA(Slum Code:-039)		
Semi Pucca	Kachha	Total
2	0	2
GOLDERPARA-2(Slum Code:-040)		
Semi Pucca	Kachha	Total
6	0	6
GOLDERPARA-3 (Slum Code:-041)		
Semi Pucca	Kachha	Total
2	0	2
DAKSHIN PALLY(Slum Code:-052)		
Semi Pucca	Pucca	Total

6	1	7
SAHAPARA(Slum Code:053)		
Semi Pucca	Kachha	Total
3	1	4
DAKSHIN PALLY PASCHIM(Slum Code:054)		
Semi Pucca	Kachha	Total
0	1	1
DAKSHIN PALLY MADHYA(Slum Code:055)		
Semi Pucca	Kachha	Total
5	0	5
BIDHAN PARA(Slum Code:-056)		
Semi Pucca	Pucca	Total
0	1	1
ASHISH COLONY(Slum Code:-063)		
Semi Pucca	Kachha	Total
5	0	5
SARAT BOSE COLONY 1(Slum Code:-064)		
Semi Pucca	Kachha	Total
9	0	9
DAKSHIN PALLY 2(Slum Code:-070)		
Semi Pucca	Kachha	Total
1	0	1
PURBACHAL(Slum Code:-071)		
Semi Pucca	Kachha	Total
9	2	11
ARUNACHAL(Slum Code:-075)		
Semi Pucca	Kachha	Total
1	0	1
DUTTA BAGAN(Slum Code:-083)		
Semi Pucca	Kachha	Total
1	0	1
THANA ROAD(Slum Code:-084)		
Semi Pucca	Kachha	Total
9	1	10
IT KHOLA(Slum Code:-085)		

Semi Pucca	Kachha		Total
9	1		10
P.K. BISWAS ROAD(Slum Code:-089)			
Semi Pucca	Kachha		Total
6	1		7
BALAK NATH TALA(Slum Code:-091)			
Semi Pucca	Pucca		Total
12	3		15
RASKHOLA BY LANE(Slum Code:-095)			
Semi Pucca	Kachha		Total
1	0		1
THANA ROAD(Slum Code:-096)			
Semi Pucca	Kachha		Total
18	0		18
MADHUSUDAN MUKHERJEE ROAD(Slum Code:-122)			
Semi Pucca	Kachha		Total
2	0		2
RAGHUNATH SHAW BASTEE(Slum Code:-097)			
Semi Pucca	Kachha		Total
15	0		15
3 NO GOVT. COLONY(Slum Code:-099)			
Semi Pucca	Kachha	Pucca	Total
4	1	1	6
P.N. MUKHERJEE BY LANE(Slum Code:-104)			
Semi Pucca	Kachha	Pucca	Total
1	2	1	4
PANCHANAN TALA BY LANE(Slum Code:-108)			
Semi Pucca	Kachha		Total
1	0		1

Most of the dwelling units have mud flooring closely followed by cement flooring. Firewood is the major source of cooking fuel in majority of the slum household.

Land Tenure status

All of the existing households are encroachment on Municipal land.

Physical Infrastructure

Infrastructure is the basic requirement of urban life and its adequacy and accessibility are two important ingredients and key contributors in the up gradation and enrichment of quality of urban life which is the primary objective of any planned development effort. These infrastructure facilities are broadly classified into two aspects:

Physical infrastructure: Water supply, Drainage, Solid waste, Roads, Electricity.

Social infrastructure: Health, School, Community Hall, Lively Hood Centre

Status of Physical Infrastructure

KHATAL BUSTEE(Slum code-001)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No
KUNBHAKAR BUSTEE (Slum code-008)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days

8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
BARIK BUSTEE(Slum code-011)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
M.P.SCHOOL BUSTEE(Slum code-012)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No

WAHED BUSTEE(Slum code-013)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No
CHANDU BUSTEE(Slum code-015)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No
DEWAN BUSTEE(Slum code-017)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected

3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

DANGAPARA CHOWDHURY MORE(Slum code-021)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

DANGAPARA GOVT. COLONY(Slum code-022)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days

8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
DANGAPARA ARUNADOY SANGHA(Slum code-113)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
SYBON ROAD(Slum code-023)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days

8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No

ANANDAPALLY(Slum code-024)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No

RAMKRISHNA PARK(Slum code-026)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected

3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

SREE PALLY(Slum code-027)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable

11. Whether Street light facility is available in the Slum	No
RAAMKRISHNA PALLY AMBAGAN(Slum code-029)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No
SREE PALLY (PASCHIM)(Slum code-032)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily

6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
SITALA MANDIR(Slum Code-033)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
RAMKRISHNA PARK ROAD(Slum code-034)	
Physical Infrastructure	Status

1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No
RAMKRISHNA PALLY 2 NO ROAD(Slum code-035)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha

9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
RAMKRISHNA PARK 2(Slum code-115)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Strom-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
NILGUNJ ROAD ORAW PARA(Slum code-038)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Strom-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected

4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No
MORAL PARA(Slum code-039)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

GOLDERPARA-2(Slum code-040)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

GOLDERPARA-3(Slum code-041)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff

7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No

DAKSHIN PALLY(Slum code-052)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No

SAHAPARA(Slum code-053)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected

2. Connectivity to City-wide Strom-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

DAKSHIN PALLY PASCHIM(Slum code-054)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Strom-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km

10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No
DAKSHIN PALLY MADHYA(Slum code-55)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No
BIDHAN PARA(Slum code-056)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No

5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
ASHISH COLONY(Slum code-063)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
SARAT BOSE COLONY 1(Slum code-064)	

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

DAKSHIN PALLY 2(Slum code-070)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days

8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No

PURBACHAL(Slum code-071)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No

ARUNACHAL(Slum code-075)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected

3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

DUTTA BAGAN(Slum code-083)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable

11. Whether Street light facility is available in the Slum	No
THANA ROAD(Slum code-084)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Garbage Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No
IT KHOLA(Slum code-085)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily

6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
P.K. BISWAS ROAD(Slum code-089)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
BALAK NATH TALA(Slum code-091)	
Physical Infrastructure	Status

1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

RASKHOLA BY LANE(Slum code-095)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha

9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
THANA ROAD(Slum code-096)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
MADHUSUDAN MUKHERJEE ROAD(Slum code-122)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected

4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

RAGHUNATH SHAW BASTEE(Slum coe-097)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

3 NO GOVT. COLONY(Slum code-099)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9. Distance from the nearest Motorable road	Less than 0.5 km
10. Internal Road	Non-motorable
11. Whether Street light facility is available in the Slum	No

P.N. MUKHERJEE BY LANE(Slum code-104)

Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4. Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff

7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No
PANCHANAN TALA BY LANE(Slum code-108)	
Physical Infrastructure	Status
1. Connectivity to City-wide Water Supply System	Partially connected
2. Connectivity to City-wide Storm-water Drainage Supply System	Partially connected
3. Connectivity to City-wide Sewerage System	Partially connected
4.Whether the slum is prone to flooding due to rains	No
5. Frequency of garbage Disposal	Daily
6. Arrangement for Global Disposal	Municipal staff
7. Frequency of clearance open drains	Once in 2 days
8. Approach Road/Lane/Constructed Path to Slum	Motorable katcha
9.Distance from the nearest Motorable road	Less than 0.5 km
10.Internal Road	Non-motorable
11.Whether Street light facility is available in the Slum	No

Majority of the household uses public taps for water supply. The situation of water supply in the slum is poor. There are presently two water tap only.

Sewerage and Storm Water Drains

According to Sectoral Plan for Drainage, Sewerage & Sanitation (2001-2025) prepared by KMPC, there is no integrated sewerage system in the municipal area. At present, each and every household is directly connected to an individual septic tank and two pit privies. According to the building rules published in November 2010 by Khardah Municipality, all building plans sanctioned, must have septic tank with soak pit. But in practice no soak pit is constructed in many buildings and the waste water is directly discharged into the surface drains.

Sanitation through septic tank is a general practice in the city where sewerage network is not available. At present, each and every household is directly connected to an individual septic tank and two pit privies. Overall lack of adequate sanitation facilities in slum areas at Khardah contributes greatly to the faecal contamination of the environment. Such contamination and the associated diseases can be spread through a variety of routes through water, soil & food. In Khardah, presently there are 2 nos. of Pay and Use Community Toilet Complex in the city. In Khardah Municipality, there is just one Crematorium.

There is no integrated sewerage system in the municipal area. There is only 76 k.m. renovated open surface drain flowing with combined sewer.

Types of sanitary in the municipal area (approximate percentage)

- Septic tank with soak pit : 20%
- Septic tank without soak pit : 60%
- Two pit pour flush latrine : 7%
- Kutcha latrine : 13%

Solid waste

As an inevitable consequence of growing population and urban lifestyle, use of disposable items, a large portion of which is non-biodegradable, is increasing. Thus management of solid waste to keep out city clean and at the same time to make ourselves able to live a healthy life has become a serious problem and Khardah municipal area is not an exception to that. As per standard, generation of solid waste in urban areas is 0.5 kg/capita/day and thus considering a total population strength of 1,16,252 persons (2001 census), the total quantity of solid waste should be 58126 kgs i.e., 58.126 ton. But according to municipal records, solid waste generated in Khardah municipal area is 80 metric ton/day which indicates a per capita generation rate of 0.68kg/day. **Basic Information:-** Some basic data and information regarding solid waste management in this municipal area are given in the next page.

Solid Waste Generation & Collection

- **Quantity of Solid Waste generated per capita / day (gm.):**- 615 gm.
- **Quantity of solid Waste generated per day (MT):**- 71.49 approx.
- **Quantity of Solid Waste collected per day (MT):**- 61.50 approx.
- **Frequency of collection:** Daily/Alternate day
- **Frequency of waste collection in slums:** Daily/Alternate day
- **Total No. of Tractors:-**11; where 7 no.s of Tractors are used for Solid Waste disposal purpose, 2 are used in Cesspool and other 2 are used for water transportation purpose.
- **No. of Trailers available:** - 10 no.s
- **Capacity of Per Trailer:** - 1.8 Metric Ton / trailer
- **No. of trips of Tractor Trailer:**
3 trips / trailer / shift; Total Shifts = 2.

- **Trip route for Trailers:** - No fixed route is followed. Route is fixed daily as per report of supervisors or Sardars who visit the wards to see waste dumping scenario in vats or other collection points.

There are total 7 no. of Sardars in 22 wards

- **No. of Hand Carts:-** 17 no.s
- **Capacity of hand carts:** 6 cu.ft. (3x2x1)
- **No. of shifts for Handcarts:** - Only one shift of handcarts from 6 a.m to 1 p.m.
- **No. of Drivers =** Total no. of Drivers are 25 where 9 no.s holds Permanent post, 6 are working as seasonal and 10 no.s are casual staffs.
- **Total no. of Vats:-**Total 57 numbers of vats were used for waste disposal purpose in Khardah municipal area, including total 51 no.s of Concrete vats and 6 no.s of Container vats located in all 22 wards.
- **Method of disposal of waste:-** Crude open dumping
- **Total no. of Labors:-**102; among them 87 no.s are permanent and 15 no.s are casual labors.
- **No. of Burning Ghats =** 1 no., wooden based. Nathupal Ghat located in Ward No.-18 , maintained by Municipality.

No. of Burial ground = 1 no. , Ground of Hari Ghosh located in Ward No.-5, maintained by Private Agency

Roads

Approach roads to the slums are motor able but roads within slum are in dilapidated condition.

Roads in front of premises

Motorable Pucca	Motorable Katcha	Non Motorable Pucca	Non Motorable Katcha
0%	25%	18%	29.5%

Electricity

Majority of the household (100%) have electricity connections, The street lights are maintained by the Municipality

Literacy level

It is observed that 112 of the population are illiterate. Literacy of the female population is less than that of the male.

Details of Social Infrastructure at a glance:**KHATAL BUSTEE(Slum Code-001)****Education & Social Infrastructure**

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production	NA

Education & Social Infrastructure

Centre	
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

KUNBHAKAR BUSTEE(Slum Code-008)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA

Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

BARIK BUSTEE(Slum code-011)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA

Education & Social Infrastructure

State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1

Education & Social Infrastructure**Women's Association/Mahila Samithis**

NA

M.P.SCHOOL BUSTEE(Slum code-012)**Education & Social Infrastructure****Pre-primary School****Anganwadi under ICDS**

Within distance less than 1 km

Municipal Pre-school

NA

Private Pre-school

NA

Primary School**Municipal**

NA

State Government

Within distance less than 0.5 km

Private

NA

High School**Municipal**

NA

Private

NA

State Government

Within distance less than 0.5 km

Adult Education Centre

NA

Health Facilities

NA

Urban Health Post

NA

Primary Health Centre

NA

Government Hospital

Within distance less than 10 km

Maternity Centre

NA

Private Clinic

NA

Registered Medical Practitioner (RMP)

NA

Ayurvedic Doctor/Vaidya

NA

Social Development/Welfare

NA

Community Hall

NA

Education & Social Infrastructure

Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

WAHED BUSTEE(Slum code-013)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA

Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

CHANDU BUSTEE(Slum code-015)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	

Education & Social Infrastructure

Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA

Education & Social Infrastructure

Youth Association	1
Women's Association/Mahila Samithis	NA

DEWAN BUSTEE(Slum Code-017)**Education & Social Infrastructure**

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA

Education & Social Infrastructure

Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

DANGAPARA CHOWDHURY MORE(Slum Code-021)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km

Education & Social Infrastructure

Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

DANGAPARA GOVT.COLONY(Slum Code-022)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA

Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA

Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

DANGAPARA ARUNADOY SANGHA(Slum code-113)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA

Education & Social Infrastructure	
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

SYBON ROAD(Slum code-023)

Education & Social Infrastructure	
Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km

Education & Social Infrastructure

Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

ANANDAPALLY(Slum code-024)**Education & Social Infrastructure**

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km

Education & Social Infrastructure

Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA

Education & Social Infrastructure

Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

RAMKRISHNA PARK(Slum code-026)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA

Education & Social Infrastructure

Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

SREE PALLY (Slum code-027)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA

Education & Social Infrastructure

High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

RAAMKRISHNA PALLY AMBAGAN (Slum code-029)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA

Education & Social Infrastructure

Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

SREE PALLY (PASCHIM) (Slum code-032)

Education & Social Infrastructure

Pre-primary School	
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA
State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA

Education & Social Infrastructure	
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1
Women's Association/Mahila Samithis	NA

SITALA MANDIR (Slum code-033)

Education & Social Infrastructure	
Pre-primary School	NA
Anganwadi under ICDS	Within distance less than 1 km
Municipal Pre-school	NA
Private Pre-school	NA
Primary School	
Municipal	NA

Education & Social Infrastructure

State Government	Within distance less than 0.5 km
Private	NA
High School	
Municipal	NA
Private	NA
State Government	Within distance less than 0.5 km
Adult Education Centre	NA
Health Facilities	NA
Urban Health Post	NA
Primary Health Centre	NA
Government Hospital	Within distance less than 10 km
Maternity Centre	NA
Private Clinic	NA
Registered Medical Practitioner (RMP)	NA
Ayurvedic Doctor/Vaidya	NA
Social Development/Welfare	NA
Community Hall	NA
Livelihood/Production Centre	NA
Vocational Training/Training cum Production Centre	NA
Street Children Rehabilitation Centre	NA
Night Shelter	NA
Old Age Home	NA
Self Help Groups/DWCUA Groups in Slum	NA
No. of Neighbourhood Groups (NHGs) in slum	NA
Slum-dwellers Association	NA
Youth Association	1

Education & Social Infrastructure**Women's Association/Mahila Samithis**

NA

RAMKRISHNA PARK ROAD (Slum code-034)**Education & Social Infrastructure****Pre-primary School****Anganwadi under ICDS**

Within distance less than 1 km

Municipal Pre-school

NA

Private Pre-school

NA

Primary School**Municipal**

NA

State Government

Within distance less than 0.5 km

Private

NA

High School**Municipal**

NA

Private

NA

State Government

Within distance less than 0.5 km

Adult Education Centre

NA

Health Facilities

NA

Urban Health Post

NA

Primary Health Centre

NA

Government Hospital

Within distance less than 10 km

Maternity Centre

NA

Private Clinic

NA

Registered Medical Practitioner (RMP)

NA

Ayurvedic Doctor/Vaidya

NA

Social Development/Welfare

NA